

# INSPECTION NOTICE

## LOCK-STITCHING ON KALIMBA

**IN PROGRESS** 21/12/2023


Call for inspection on Kalimba following a deviation from manufacturer instructions at one of our splice certified distributors. **For your safety we ask you to inspect the lock-stitching** of your splice.

### How to inspect ?

Take the time to **inspect the lock-stitching** as shown below.

### Inspection procedure

if the **lock-stitching** is missing on your rope, stop use and contact your dealer.



### Any questions ?

Contact your dealer.

 [mycourant.com](https://mycourant.com)

 [courantverticalliving](https://www.facebook.com/courantverticalliving)

 [couranttreecare](https://www.instagram.com/couranttreecare)



# AVIS D'INSPECTION COUTURE KALIMBA



**Courant**  
VERTICAL LIVING

**EN COURS** 21/12/2023

Appel à l'inspection des épissures Kalimba suite à une déviation de nos instructions chez l'un de nos distributeurs certifiés. **Pour votre sécurité, nous vous demandons d'inspecter immédiatement la couture** de votre épissure.

## Comment l'inspecter ?


Prenez le temps de vérifier **les points de couture** comme ci-dessous.

## Mode opératoire d'inspection


Si la **couture** est manquante, n'utilisez plus votre corde et contactez votre revendeur.



Résultat non-conforme  
**Aucune couture**



Résultat conforme



Résultat conforme



A titre de référence  
uniquement

## Des questions ?

Contactez votre revendeur.

 [mycourant.com](https://mycourant.com)

 [courantverticalliving](https://www.facebook.com/courantverticalliving)

 [couranttrecare](https://www.instagram.com/couranttrecare)